Under Review Notification

Raised By: Vanessa Morel Product #: H-E-C622G4001101

Date: 2019.11.01 Product Name: FREQUENCY ADAPTER ADJUSTMENT TOOL

		"Y" or "N" Required for Each Part									
		Do not leave blank									
Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	DO NOT SHIP	Red Tag/Quarantine Stock	Advise Customers		Quarantine Tooling (Jigs, Fixtures, etc.)	Re-Work Stock	IPP Under Review (Enginer Signoff Required.)	Put Product Specifications Under Review ("Bluefiles")	Reserved ECN / URF Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
H-E-C622G4001101	H-E-C622G4001101 Rev	Υ	Υ	N	Υ	Υ	N	Ν	N	19-1193	See below

Description of Issue:

Issues stated on ADR (Fit, manufacturing, material, finishes issues)

H-E-C622G4001101 and items -01,-03, -05, -07, -21, -23, -25 and -27 must be put on **HOLD** in Plex

H-E-C622G4001101 Finish good stock must be put in quarantine

Item -01,-03, -05, -07, -21, -23, -25 and -27 stock must be put in quarantine

No new manufacturing is permitted until Engineering release new Rev

Can remain on website with a note to contact sales for a quote. They must **NOT** be able to put the tool into cart

'P" Part must be put on HOLD in Plex as well

Distribution: VP Operations Director of Engineering Customer Support Manager Technical Support

Director of OperationsChief EngineerProduction EngineersProduct Manager - Solutions ProviderDirector Quality AssuranceEngineering Project ManagersProduction PlannersSupply Chain Director / Senior Buyer

QC Coordinator Engineering Clerk Purchasing Manager Marketing Eugene